

Drainage Issues Floritam Sod

Problem Drainage Areas



Common Drainage Issue



Swaled Driveways



Cul De Sac Issues




Dead Sod Due to Standing Water



Re-Grading & Re-Sodding



Thatch



Grass Plant

Old Grass Clipping
(Will soon decompose.)

Thatch Layer
(Too thick)

Grass Roots

Soil

Severe Thatch Buildup



Dethatching In Progress



GPS VIDEO CAMERA



GPS Video Logging

The screenshot displays the VIRB Edit software interface. The main window is split into two panels. The left panel shows a video of a golf course with a large water hazard in the foreground. The right panel shows a map overlay with a black line indicating the recorded path. The map includes street names such as Deborah Ct, Sandpiper Dr, Raven Ct, Kinglet Dr, Grebe Dr, Pine-Sykin Dr, Thrasher Dr, Sea Fan Dr, Osprey, Turtle Dove Blvd, Los Alamos Dr, Suzi St, and La Costa Island Dr. A red circle on the map indicates the current location. The video player shows a speedometer with a reading of 18 mph and a compass. The timeline at the bottom shows a duration of 0:14 / 11:47. The interface includes various controls such as play, stop, and trim buttons, and a clip library on the left.

VIRB Edit

Install Update | About... | - | ☐

Video Gallery | My Video | Export | Upload

Map | Sat

0:10 / 0:00:14

18 mph

272°

0:14 / 11:47

Drag and drop clips here to add to timeline

Clip Library

All

Last Import

Trim Left | Split | Trim Right

GPS Log

Adjust