


Post-Ian Seawall Damage Assessment

Seawall Failures

- High Priority
- Medium Priority
- Low Priority



Date Generated: 1/26/2023



Based on Post-Ian Seawall Initial Damage Assessment GIS surveys and detailed Damage Assessment Reports from field inspections completed by City of Punta Gorda Public Works Canal Maintenance Staff between 9/28/2022 and 1/24/2023.

File: Hurricanelan_HighPriority_ZoneMaps_Landscape.mxd



Zone: BSI-S

Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri China (Hong Kong), swisstopo, © OpenStreetMap contributors, and the GIS User Community