



**Post-Ian Seawall Damage Assessment**

**Seawall Failures**

- █ High Priority
- █ Medium Priority
- █ Low Priority

Based on Post-Ian Seawall Initial Damage Assessment GIS surveys and detailed Damage Assessment Reports from field inspections completed by City of Punta Gorda Public Works Canal Maintenance Staff between 9/28/2022 and 1/24/2023.

Date Generated: 1/26/2023



**Zone: PGI-NW2**

Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, OpenStreetMap contributors, and the GIS User Community