



Post-Ian Seawall Damage Assessment
Seawall Failures
 — High Priority
 — Medium Priority
 — Low Priority



Date Generated: 1/26/2023

Based on Post-Ian Seawall Initial Damage Assessment GIS surveys and detailed Damage Assessment Reports from field inspections completed by City of Punta Gorda Public Works Canal Maintenance Staff between 9/28/2022 and 1/24/2023.



Zone: BSI-N

Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, US GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China, OpenStreetMap contributors, and the GIS User Community

File: HurricaneIan_AllPriority_ZoneMaps.mxd