



**Legend**

**Replacement Priority**

- █ High
- █ Med
- █ Low
- █ Restored

**Replacement Sequence**

- L3 Work Underway
- L5 Work Completed

**Zone: PGI-NE2**

**Post FEMA Inspection  
IRMA Seawall Failure Locations**

Date Generated: 10/3/2018

Please review the City of Punta Gorda website for additional details regarding this exhibit.

